



- RECOMMENDED WIRING IS TO PUT EACH MOTOR ON ITS OWN BREAKER
- 3A FUSE SIZE MAY NEED TO BE INCREASED FOR PROTECTION CHECK MOTOR SPECS.